
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20161027, Public Works Infrastructure Permit - Commercial
TWIN LAKES INSURANCE
Address: 2641 NE MCBAINE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Erosion Sediment Control (ESC) Inspection	Tom Chandler	Failed	Tuesday, August 15, 2017

Corrective Action Required

- 1 There are problems with the erosion control devices on your site. Tom Chandler 08/15/2017 1:35 PM Silt has left the property and is in the roadway. Will need to clean silt and repair silt fence that has failed.

Comments:
