

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20161027, Public Works Infrastructure Permit - Commercial
TWIN LAKES INSURANCE
Address: 2641 NE MCBAINE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Erosion Sediment Control (ESC) Inspection	Tom Chandler	Partial	Thursday, August 17, 2017

Corrective Action Required

- 1 There are problems with the erosion control devices on your site. Tom Chandler 08/15/2017 1:35 PM Silt has left the property and is in the roadway. Will need to clean silt and repair silt fence that has failed.
Tom Chandler 08/16/2017 10:39 AM The silt fence still needs repaired and area to be vegetated. Rain has been falling off and on most of the morning. Someone has started to remove from roadway. Began raining heavy again and was not able to finish removing silt from roadway.
Tom Chandler 08/17/2017 11:19 AM Contractor still needs to correct silt fence and clean roadway. Someone had begun working on cleaning roadway while I was there. Will go back to inspect progress in the afternoon.

Comments: