

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20170443, Building Permit - Residential

Address: 2212 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822214 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822216 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822210 SW BURNINGWOOD LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Tuesday, August 22, 2017

Corrective Action Required

1 Misc

OK to insulate.

ALL UNITS:

1. Nail top-plate straps where bored for DWV.

UNIT 2216:

1. Gap between top of fire-rock and roof deck, at ridge.

UNIT 2214:

1. 1st FLR: Missing nails in joist hanger over stair.
2. 2nd FLR: Pan / Fireblock top and bottom of duct chase located next to short stair to rear bedroom.
3. 2nd FLR: Bath fan duct.
4. 2nd FLR: Move DWV that is directly over attic access.

UNIT 2212:

1. 1st FLR: Security blocks - rear door.
2. 2nd FLR: Pan / Fireblock top and bottom of duct chase located next to short stair to rear bedroom.
3. 2nd FLR: Bath fan duct.

UNIT 2210:

1. Complete installation of main electric disconnect and feeder conductors.

**Electrical Service
Inspection - Residential**

Dale Carter

Failed

Tuesday, August 22, 2017

Corrective Action Required

1

Misc

Complete installation of main disconnect and feeder conductors to Unit 2210.

**Rated Assembly
Inspection**

Dale Carter

Failed

Tuesday, August 22, 2017

Corrective Action Required

1

Misc

Gap between top of fire-rock and roof deck in Unit 2216, at ridge.

Comments: