

---

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #: PRPWFC20172294, Public Works Infrastructure Permit - Commercial

INSTANT AUTO - PARKING LOT EXPANSION

Address: 2151 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	John DiMauro	Partial	Thursday, August 24, 2017

Informational

1 John DiMauro 07/24/2017 3:42 PM  
Erosion control devices are installed and intact according to the plans.

Informational

2 John DiMauro 07/27/2017 3:50 PM  
Sediment fence is intact. No debris washing out.

Informational

3 John DiMauro 08/07/2017 3:33 PM  
Sediment fence is intact. No debris washing out.

Informational

4 John DiMauro 08/08/2017 3:29 PM  
Sediment fence is intact.

Informational

5 John DiMauro 08/17/2017 1:44 PM  
The sediment fence is intact.

Corrective Action Required

6 John DiMauro 08/22/2017 10:09 AM  
There are problems with the erosion control devices on your site. There are two sections of the sediment fence that have failed. The fence needs to be corrected.

Resolved

7 John DiMauro 08/24/2017 10:29 AM  
The sediment fence has been repaired.

**Comments:**

---