PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171691, Building Permit - Residential Address: 4717 NE GATEWAY DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Friday, August 25, 2017

Residential

Corrective Action Required

1 Misc FRAMING:

-FRAME CS PF WALLS PER PLAN

-BRACE INTERIOR WALLS PER PLAN

-HAVE ENGINEER OK/ADDRESS THE OVERNOTCHED DOUBLE

JOIST AT STAIR WALL THAT CARRIES LVL LOAD

-AT FRONT BED&BATH, MOVE THE ROOF SUPPORT STRUTS TO

WALL WITH DOUBLE JOIST BELOW

-INSTALL EXTERIOR DOOR FRAMES PER LS SECURITY CODE

-SOLIDBLOCK ALL LAPPED JOISTS ABOVE I BEAMS

-PROVIDE FULL SOLIDBLOCKING SUPPORT UNDER I BEAM (I

BEAM BETWEEN KITCHEN AND LIVING RM) POINT LOAD

-FIREBLOCKING: FB THE TRIANGULAR SPACE AT FIREPLACE SHELF FROM ROOF; FB FLOOR AT TRAP; FB BASEMENT WALL PER CODE; FB DEAD SPACE FROM FURDOWN SPACE AT BASEMENT TUB

MECHANICAL:

-INSTALL B-VENT SHIELD FOR HEARTH FIREPLACE

-FIX THE DENTED B-VENT

-CONNECT DUCT TO BATHFAN AT FRONT BATH

ELECTRICAL:

-INSTALL A WALL RECEPTACLE IN HALLWAY OUTSIDE BASEMENT BEDS

PLUMBING:

-STRAP OVERBORED WALL TOP PLATE AT FRONT BATH

**OK TO INSULATE

Gas Service Inspection - Khanh Nguyen

Passed

Friday, August 25, 2017

Residential

Electrical Service

Khanh Nguyen

Passed

Friday, August 25, 2017

Inspection - Residential

Erosion Control

Khanh Nguyen

Partial

Friday, August 25, 2017

Corrective Action Required

1 DCM2 Erosion Control

8/25/17-EROSION CONTROL IN COMPLIANCE

Comments: