
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20172294, Public Works Infrastructure Permit - Commercial

INSTANT AUTO - PARKING LOT EXPANSION

Address: 2151 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Site Visit	John DiMauro	Partial	Monday, August 28, 2017

Informational

- 1 John DiMauro 07/24/2017 3:41 PM
Crews have started grading for the parking lot.

Informational

- 2 John DiMauro 07/25/2017 11:12 AM
Kaw Valley crew is on site grading for the parking lot expansion.

Informational

- 3 John DiMauro 07/26/2017 3:39 PM
Kaw Valley crew is on site grading for the parking lot expansion.

Informational

- 4 John DiMauro 07/27/2017 3:51 PM
No activity.

Informational

- 5 John DiMauro 07/28/2017 10:26 AM
No activity this morning.

Informational

- 6 John DiMauro 07/31/2017 3:41 PM
Kaw Valley crew is on site grading for the parking lot.

Informational

- 7 John DiMauro 08/01/2017 2:06 PM
Kaw Valley crew is on site grading for the parking lot.

Informational

- 8 John DiMauro 08/07/2017 3:32 PM
No activity.

Informational

9 John DiMauro 08/08/2017 3:28 PM
No activity.

Informational

10 John DiMauro 08/09/2017 3:46 PM
No activity today.

Informational

11 John DiMauro 08/17/2017 1:42 PM
No activity.

Informational

12 John DiMauro 08/22/2017 10:13 AM
Brad George with Kaw Valley is going to get the sediment fence repaired this week.

Informational

13 John DiMauro 08/28/2017 10:30 AM
No activity.

DEI-Erosion Sediment Control John DiMauro
(ESC) Inspection

Partial

Monday,
August 28,
2017

Informational

1 John DiMauro 07/24/2017 3:42 PM
Erosion control devices are installed and intact according to the plans.

Informational

2 John DiMauro 07/27/2017 3:50 PM
Sediment fence is intact. No debris washing out.

Informational

3 John DiMauro 08/07/2017 3:33 PM
Sediment fence is intact. No debris washing out.

Informational

4 John DiMauro 08/08/2017 3:29 PM
Sediment fence is intact.

Informational

5 John DiMauro 08/17/2017 1:44 PM
The sediment fence is intact.

Corrective Action Required

6 John DiMauro 08/22/2017 10:09 AM
There are problems with the erosion control devices on your site. There are two sections of the sediment fence that have failed. The fence needs to be corrected.

Resolved

7 John DiMauro 08/28/2017 10:28 AM
The sediment fence has been corrected and is intact.

Comments:
