

Inspection Summary

Permit #: PRRES20170812, Building Permit - Residential
Address: 1622 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Sewer Service Inspection - Residential	Dale Carter	Passed	Thursday, August 31, 2017

Erosion Control	Mike Copeland	Failed	Thursday, August 31, 2017
------------------------	---------------	--------	---------------------------

Corrective Action Required

1	Misc	-EROSION CONTROL IN THE FRONT NEEDS TO EXTEND TO THE EAST WHERE AREA WAS DISTURBED FROM CONSTRUCTION FROM THIS LOT. -REAR OF THE LOT IS DISCHARGING INTO THE SECONDARY MEANS OF ESC AND NEEDS TO BE PROTECTED.
---	------	---

Comments: