Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20170922, Building Permit - Residential Address: 1324 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Thursday, August 31, 2017

Residential

Corrective Action Required

L Misc -FIREBLOCKING: FB BASEMENT BATH CLOSET WALL FROM

FURDOWN SPACE; FB BATH SINK WALL FROM FURDOWN SPACE

-SUPPORT TOP OF HIPS ABOVE MASTER BATH
**ADD A BLOCK TO CATCH THE TOP OF THE HIP

-PROVIDE MIN. 6 FT 8 INCHES HEADROOM CLEARANCE ABOVE STAIR, MEASURED VERTICALLY FROM TREAD NOSE-NOSE PLANE **INSTALL THE SINGLE PLY LVL HEADER TO CARRY THE END LOAD OF THE JOISTS. THE LVL HEADER CAN BE OFFSET INWARD SO THE CEILING CAN BE BEVELED.

-ANCHOR BASEMENT SILL PLATES WITHIN 12" OF BREAKS, INCLUDING NEAR DOORS
**NOT DONE AT ALL

-INSTALL SINGLE LVL ABOVE STORAGE RM PER PLAN

-BASEMENT EXTERIOR DOOR: FILL IN GAPS BEHIND HINGES AND AT STRIKE PLATE SIDE PER LS SECURITY CODE

**FILL IN WITH WOOD, NOT FOAM

***OK TO INSULATE

Comments: