

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

Permit #: PRPWFC20172147, Public Works Infrastructure Permit - Commercial  
B&J Peerless Addition  
Address: 2301 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

**Inspection Item:**

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
DEI-Erosion Sediment Control (ESC) Inspection	John DiMauro	Partial	Monday, September 11, 2017

Informational

1 John DiMauro 07/25/2017 11:31 AM  
The silt fence is installed and intact according to the plans.

Informational

2 John DiMauro 07/27/2017 3:42 PM  
The sediment fence is intact. No debris washing out.

Informational

3 John DiMauro 08/07/2017 3:36 PM  
The sediment fence is intact. No debris washing out.

Informational

4 John DiMauro 08/08/2017 3:24 PM  
The sediment fence is intact. No debris washing out.

Corrective Action Required

5 John DiMauro 08/22/2017 10:28 AM  
There are problems with the erosion control devices on your site. There is a section of the sediment fence that has failed due to the rain event. This fence needs to be fixed and corrected.

Informational

6 John DiMauro 09/11/2017 3:46 PM  
Erosion control devices are intact.

**Comments:**

