



September 7, 2017

Shaw Construction Inc.
PO Box 166
Napoleon, MO 64074

Re: ¹⁵²²5022 SW Blackstone Place
Lot 131, Napa Valley
Lee's Summit Permit #2017-1140

Apex Engineers, Inc. observed the excavation for the proposed house located at the address above. The sub-grade bearing capacity was evaluated.

The excavation terminates on organic and imported soil that will not adequately support the proposed house. Test pits indicated that original clay, with a minimum bearing capacity of 2000 psf, can be found within 12" to 48" below the desired sub-grade.

Our firm recommends further trenching/digging the footings and pier pads (for their required width). The base of the footings shall be below the fill line, free of organic material and bear on the native clay (to be verified). The base of the trench shall not exceed a 10:1 slope. All footings and pier pads shall bear on the same bearing material, as it is pertinent to provide uniform bearing conditions beneath all footings and pads to help minimize differential settlement. If the trenches are poured separately from the footing, then place 48" long dowels every 24" along the trench and bend into the footing forms.

Upon completion of the above recommendation, the footing sub-grade shall be verified to be capable of supporting an allowable bearing capacity of 2000 psf subject to the "Recommendations" and "Limitations" given in this report.

The above recommendation is based on bearing capacity only. Our firm has not been retained to determine the shrink/swell capacity of the soil and therefore cannot be held responsible for the volumetric changes of the soil (including below the basement slab). As with all houses on clay soils, the following precautions shall be followed to mitigate the potential for expansive clay issues. Install a sump pit and pump connected to the exterior foundation drain. Isolate the basement steel column to concrete pad connection from the basement slab. Non-load bearing basement stud walls shall be framed to allow 1" of vertical movement.

Slope stability and final grading shall be the responsibility of others. The contractor shall take the necessary steps to stabilize the lot (i.e. proper grading & slope per code, retaining walls, etc.).

Basement Slab

The basement slabs shall be structural.

- Add (2) 36"x36" slab support pads per the attached layout. Reinforce with (4) #4 bars each way.
- Place 5" concrete slab w/ #4 bars at 12" o.c. each-way on 1-1/2" chairs.



- Add (4) 10'-0" long #4 bars each-way over the column pads and slab support piers. Place with 1" to 1-1/2" slab top cover (3" chairs). See attached slab details for clarity.
- The perimeter of the slab shall bear on the foundation as follows:
 - Minimum 3" keyway or footing, OR
 - Drill 5" deep and pin to foundation with #4 bars at 12" on center.

RECOMMENDATIONS

The surface drainage must be designed to effectively move water away from the home and to prevent ponding. Poor drainage near a structure can also contribute to settlement problems. The failure to control drainage can result in the saturation and weakening of the surrounding soil causing settlement. A proper drain system, consisting of a drain tile draining to a sump pit and pump shall be installed and maintained in compliance with Section R405 and R406 of the International Residential Code. A build-up of water beneath the foundation can cause heaving of the foundation (pier pads) and basement slab resulting in sheet rock cracks and damage to the structure.

Due to the unpredictable nature of expansive clay soils, no guarantees can be made as to if and when future movement may occur. However, precautionary measures can be taken. Poor drainage increases the stresses on foundation walls, and therefore, a proper grade must be maintained away from the foundation. A positive slope of 1 inch per foot drop for 6 to 10 feet away from the house is required. Rain gutters and downspouts with extensions should be installed to direct water safe distances away from the house and from existing structures that could be adversely affected. Proper watering of the foundation system should also be maintained throughout the year, especially during extremely dry periods. In addition, all permanent slopes should be no steeper than 3:1 (horizontal to vertical) to help ensure their future stability and the accommodation of normal mowing equipment.

Apex Engineers, Inc. cannot be held responsible for the impact and/or damages caused to the structure if the aforementioned recommendations are not followed and maintained.

LIMITATIONS

The scope of our services was only to visually observe and report the existing bearing conditions (capacity only) beneath the foundation elements for the new home. When making visual observations, it should be clearly understood that certain assumptions must be made regarding the existing conditions without the aid of drilling and/or testing, which could reveal additional information that could change the recommendations and conclusions given in this report. No evaluation of slope stability, foundation wall backfill, slab-on-grade support, pavements, retaining wall structures or the suitability of any material removed from the basement excavation for any particular purpose was made unless specifically addressed herein. As a result, Apex Engineers, Inc. cannot be held responsible for the impact of those conditions on the project or future performance of the structure. Finally, a standard footing inspection should be made to verify the actual bearing conditions prior to the placement of reinforcing steel and concrete.

Shrink, swell characteristics are inherent with all clay soils and can adversely affect or jeopardize the performance of the foundation system. Apex Engineers, Inc. has not been retained to evaluate the potential expansive properties of any existing bearing material(s). Apex Engineers, Inc.'s services are not insurance, nor can it guarantee or predict future



September 7, 2017
5022 SW Blackstone Place
3 of 3

movement caused by the natural movement attributed to the shrinking and swelling of clay sub soils. Therefore, Apex Engineers, Inc. cannot be held responsible for future movement and/or damage to the structure associated with such movement (including, but not limited to, foundations elements supported by continuous strip footings, isolated pier pads, or drilled piers). The contractor shall retain sole liability and responsibility for the quality of work, for adhering to plans, specifications, appropriate codes, and for repairing defects, deficiencies, or damages regardless of cause and/or when they are found. Apex Engineers, Inc. has performed our services in a manner consistent with the standard of care and skill ordinarily exercised by firms of our type practicing under similar conditions at this time and locality.


To the fullest extent permitted and allowed by law, Apex Engineers, Inc.'s client shall indemnify and hold harmless Apex Engineers, Inc. and sub-consultants from and against all damage, liability and costs, including reasonable attorney's fees and cost of defense, to the extent caused by the performance of the services under this report, excepting only those damages, liabilities or costs attributable to the sole negligence or willful misconduct of Apex Engineers, Inc.

The recommendations and conclusions given in this report are based on the observed conditions at the time of this site visit. These conditions may be altered over time and/or with changes in the weather. If ground water ponds in the basement excavation, soft soil conditions may require further excavation and/or filling to provide uniform support beneath all the footings and floor slab. Therefore, if water ponds in this excavation or other changes occur that could affect any of the recommendations given in this report, Apex Engineers, Inc. shall be called back and allowed to re-evaluate our previous recommendations and/or conclusions. If changes in the condition of the site occur and Apex Engineers, Inc. is not allowed the opportunity to re-evaluate the site to respond to any of these changes, our firm cannot be responsible for the effect of any of the conditions that differed from those reported herein.

The scope of our services does not include any environmental assessment (such as, but not limited to mold, mildew, presence of hazardous or toxic materials in the soil, surface water, ground water, etc.). An environmental specialist should be consulted for these types of issues.

Please call if Apex Engineers, Inc. can be of further assistance.

Best Regards,
Apex Engineers, Inc.



Enclosure - Plan Layout and Details


cc: City of Lee's Summit

Denver, CO 720.588-3222

Kansas City, MO 816.421-3222

Lawrence, KS 785.337-3222

apex-engineers.com



APEX ENGINEERS
 1800 BALTIMORE AVE. SUITE 102
 KANSAS CITY, MO 64108
 PH: 816.427.3222
 FX: 816.427.1050
 www.apex-engineers.com

STRUCTURAL DESIGN REVIEW

KANSAS ENGINEERING LICENSE:
 NO. 0000000000
 MISSOURI ENGINEERING LICENSE:
 20330-04673

PROJECT: 5022 SW Blackstone Place
Lot 131, Napa Valley

CLIENT: Shaw Construction

PROJECT #

DRAWING NAME



LAYOUT

DATE: COMMENTS:

DRAWN BY: APEX
CHECKED BY: —

SHEET #

1 OF 2



SLAB SUPPORT LAYOUT
NOT TO SCALE

