

## FIRE DEPARTMENT

## **PLANS REVIEW CONDITIONS**

Permit No: PRCOM20171199

Project Title: STANLEY EVENT CENTER

Location:

308 SE DOUGLAS ST, LEES SUMMIT,

MO 64063

Type of Work:

Occupancy Group: A-2

Description: TENANT FINISH FOR NEW

**BANQUET HALL** 

\*\*drawings are in plan review file

Construction Type: Type IIB (Unprotected)

Map Page: 195G

Date: September 18, 2017

Applicant:

ADVANTAGE FIRE PROTECTION SYSTEMS INC

404 B NW 11TH ST

BLUE SPRINGS, MO 64015

Primary: (816) 224-3400

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review Reviewed By: Joe Dir Released for Construction

2. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed.

ACTION REQUIRED:(verified at inspection)

The exisiting fire sprinkler system shall be current with all required service / maintenance. A current service tag shall be posted on the systems riser.

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.