

Inspection Summary

Permit #: PRCOM20161750, Building Permit - Commercial
Address: 783 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Friday, September 22, 2017

Partial Correction

1	Misc	<p>OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X MOLD-TOUGH GWB RATED ASSEMBLIES AT STAIRWELLS:</p> <p>NORTH STAIRWELL:</p> <p>BASEMENT LEVEL 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS</p> <p>FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS;</p> <p>SECOND FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS; 2ND LAYER;</p> <p>THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS; 2ND LAYER PRE-ROCK AT JOIST BAYS; 2ND LAYER AT WELL FACE;</p> <p>4TH FLOOR: 1ST LAYER @ WELL FACE; 2ND LAYER AT WELL FACE;</p> <p>SOUTH STAIRWELL:</p> <p>FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS;</p> <p>SECOND FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS; 2ND LAYER;</p>
---	------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CODES ADMINISTRATION

Partial Correction 2 Misc	<p>THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS; 2ND LAYER PRE-ROCK AT JOIST BAYS; 2ND LAYER AT WELL FACE;</p> <p>4TH FLOOR: 1ST LAYER @ WELL FACE; 2ND LAYER @ WELL FACE;</p> <p>OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X MOLD-TOUGH GWB RATED ASSEMBLIES AT ELEVATOR:</p> <p>2ND FLOOR: 1ST & 2ND LAYERS PRE-ROCK;</p> <p>3RD FLOOR: 1ST & 2ND LAYER PRE-ROCK AT JOIST BAYS;</p>
Partial Correction 3 Misc	<p>1ST LAYER WELL FACE FULL HEIGHT + 1ST LAYER AT CEILING; 2ND LAYER WELL FACE FULL HEIGHT + 2ND LAYER AT CEILING; [3RD LAYER AT CEILING + HAT CHANNEL;</p> <p>OK TO COVER WHEN READY 5/8" TYPE X GWB PRE-ROCK AT SHOWERS/TUBS AT:</p> <p>4TH FLOOR</p> <p>3RD FLOOR</p> <p>2ND FLOOR</p> <p>1ST FLOOR</p>
Partial Correction 4 Misc	<p>2ND FLOOR ELECTRICAL CLOSET: OK TO COVER FIRST LAYER GWB; [2ND LAYER ADJACENT TO ELEVATOR;</p> <p>[BASEMENT IT ROOM: ONE LAYER GWB;</p>
All Rough Inspection - Commercial	John Borns Partial Friday, September 22, 2017
Partial Correction 2 Misc	<p>OK TO COVER WHEN READY CEILING & WALL FRAMING & ENCLOSED SYSTEMS AT:</p> <p>4TH FLR ALL UNITS/SPACES INCLUDING STAIRWELLS</p> <p>[3RD FLR ALL UNITS/SPACES INCLUDING STAIRWELLS</p> <p>[2ND FLR ALL UNITS/SPACES INCLUDING STAIRWELLS</p>
Partial Correction 3 Misc	<p>RC CHANNEL IN PLACE AT CEILING & WALLS AT:</p> <p>[4TH FLOOR</p>
Partial Correction 4 Misc	<p>SHEAR WALL OK TO COVER WHEN READY AT:</p> <p>BASEMENT SOUTH STAIRWELL</p>

Comments: