

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20170806, Building Permit - Residential

Address: 1836 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Tuesday, September 26, 2017

Corrective Action Required

- | | | |
|---|------|--|
| 1 | Misc | 1. BSMT: Firestop furrouts and penetrations.
3. BSMT: Firestop top of deadspace behind shower.
6. 1st FLR: Firestop top of duct chase.
9. GARAGE: Need attic access. *Finish framing. **Need joist hangers.
10. 2nd FLR: Ridge is supported on a non-load-bearing wall. *The Engineer's recommended repairs have not been completed.
12. ALL: Elec. nail guards.
13. 2nd FLR: Protect NM within 6' attic access.
14. ALL: Top-plate straps where bored for DWV should be nailed (not fastened with drywall screws). |
|---|------|--|

Comments: