## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRRES20171753, Building Permit - Residential Address: 1824 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Gas Service Inspection - Dale Carter Failed Wednesday, September 27,

Residential 2017

Corrective Action Required

1 Misc REPAIR SILT FENCE AT FRONT, ADD GRAVEL TO ENTRANCE DRIVE,

& PERFORM STREET CLEAN-UP BEFORE FURTHER INSPECTION.

1. No pressure.

2. Bond gas pipe.

**Erosion Control** Dale Carter Failed Wednesday, September 27,

2017

Corrective Action Required

1 Misc REPAIR SILT FENCE AT FRONT, ADD GRAVEL TO ENTRANCE DRIVE,

& PERFORM STREET CLEAN-UP BEFORE FURTHER INSPECTION.

**Comments:**