Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161750, Building Permit - Commercial Address: 783 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Mark Harding Partial Wednesday, September 27,

Inspection 2017

Partial Correction

1 Misc OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X

MOLD-TOUGH GWB RATED ASSEMBLIES AT STAIRWELLS:

NORTH STAIRWELL:

BASEMENT LEVEL 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK

AT JOIST BAYS

FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT

JOIST BAYS;

SECOND FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST

BAYS; 2ND LAYER;

THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST

BAYS; 2ND LAYER PRE-ROCK AT JOIST BAYS; 2ND LAYER AT WELL

FACE;

4TH FLOOR: 1ST LAYER @ WELL FACE; 2ND LAYER AT WELL FACE;

SOUTH STAIRWELL:

BASEMENT 1ST LAYER

FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT

JOIST BAYS;

SECOND FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST

BAYS; 2ND LAYER;

THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS; 2ND LAYER PRE-ROCK AT JOIST BAYS; 2ND LAYER AT WELL

FACE;

4TH FLOOR: 1ST LAYER @ WELL FACE; 2ND LAYER @ WELL FACE;

Partial Correction

2 Misc OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X

MOLD-TOUGH GWB RATED ASSEMBLIES AT ELEVATOR:

2ND FLOOR: 1ST & 2ND LAYERS PRE-ROCK;

3RD FLOOR: 1ST & 2ND LAYER PRE-ROCK AT JOIST BAYS;

1ST LAYER WELL FACE FULL HEIGHT + 1ST LAYER AT CEILING; 2ND LAYER WELL FACE FULL HEIGHT + 2ND LAYER AT CEILING; 3RD LAYER AT CEILING + HAT CHANNEL; [4TH LAYER AT CEILING OK

TO TAPE, MUD AND FIRE-STOP

Partial Correction

3 Misc OK TO COVER WHEN READY 5/8" TYPE X GWB PRE-ROCK AT

SHOWERS/TUBS AT:

4TH FLOOR 3RD FLOOR 2ND FLOOR 1ST FLOOR

Partial Correction

4 Misc 2ND FLOOR ELECTRICAL CLOSET: OK TO COVER FIRST LAYER

GWB; [2ND LAYER ADJACENT TO ELEVATOR;

BASEMENT IT ROOM: ONE LAYER GWB; [2ND LAYER GWB

3RD FLOOR RC CHANNEL UNITS AND CORRIDOR.

All Rough Inspection - Mark Harding Partial Wednesday, September 27,

Commercial 2017

Partial Correction

1 Misc OK TO COVER WHEN READY CEILING & WALL FRAMING &

ENCLOSED SYSTEMS AT:

4TH FLR ALL UNITS/SPACES INCLUDING STAIRWELLS
3RD FLR ALL UNITS/SPACES INCLUDING STAIRWELLS
2ND FLR ALL UNITS/SPACES INCLUDING STAIRWELLS
1ST FLR ALL UNITS/SPACES INCLUDING STAIRWELLS

Partial Correction

2 Misc RC CHANNEL IN PLACE AT CEILING & WALLS AT:

[4TH FLOOR [3RD FLLOR

Partial Correction

3 Misc SHEAR WALL OK TO COVER WHEN READY AT:
BASEMENT SOUTH STAIRWELL

Corrective Action Required

Misc BSMT-ROUGH

SEALL ALL PENETRAIONS BETWEEN GARAGES.

G13,14,16

-SUPPORT DWV G7

-SEAL 3" DWV AT TOP PLATE SOUTH OF SOUTH STAIRWAY AT

CORRIDOR.

Comments: