

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Matt Munger	Failed	Friday, October 06, 2017

## Corrective Action Required

1 Matt Munger 10/06/2017 2:37 PM Your project is in violation of the Erosion and Sediment control policy.

Silt fence is not intact according to the plans around the site. There is no protection around the storm inlets. ESC devices need to be maintained throughout the duration of the project.

## **Comments:**