Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171228, Building Permit - Residential

Address: 617 NW LILAC PL, Unit:B, LEES SUMMIT, MO 64081619 NW LILAC PL, LEES SUMMIT, MO 64081615 NW LILAC PL, Unit:B, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Dale Carter Failed Thursday, October 12, 2017

Residential

Corrective Action Required

1 Misc 1. Nailing pattern on party wall and patch hole.

2. Install basement window.

3. Support DWV in basement at least every 4'.

4. Bond gas pipe.

Electrical Service Dale Carter Passed Thursday, October 12, 2017

Inspection - Residential

Gas Service Inspection - Dale Carter Failed Thursday, October 12, 2017

Residential

Corrective Action Required

1 Misc UNIT 615 ONLY:

Pressure OK. Failed because pipe not bonded.

Comments: