## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

## Permit #:PRCOM20170499, Building Permit - Commercial Address: 910 NW BLUE PKWY, Unit:D, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspectior	1:	Inspector:	Outcome:	Date:	
Occupano Codes Co	cy Inspection - mmercial	John Borns	Failed	Wednesday, October 18, 2017	
Corrective Action Required 1 Misc Corrective Action Required			RESOLVE FIRE DEPT ISSUES		
2	Misc		- CLOSE UNUSED OPENII - NUMBER BREAKER POS - NEC 408.4: LABELING C PANEL(S): EACH BREAKE LEGIBLE, SPECIFIC. IF PA POSITIONS ON PANEL FF OR CONTINUATION SYM	NGS WITH LISTED PLUGS SITIONS OF ELECTRICAL CIRCUIT POSITIONS AT TR POSITION MUST BE LABELED. MUST BE NEL SCHEDULE IS USED NUMBER RONT PER SCHEDULE. NO DITTO MARKS IBOLS EXCEPT @ MULTIPLE POLE ED BREAKERS "SPARE". LABEL	
Corrective Action Required					
3	Misc		RECEPTACLE / SWITCH B	.5-6 SET-BACK OF ELECTRICAL BOXES: MUST BE FLUSH WITH RFACE; 1/4" MAXIMUM SET-BACK @ RFACES.	

Comments: RESTROOM SIGN NOT CORRECT.