## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20172129, Building Permit - Commercial Address: 834 SW BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Not Ready Thursday, October 19, 2017

Corrective Action Required

1 Misc COMPLETE REPAIR OF EXISTING WALL FRAMING FOR STREGTH

AND TRUENESS. PROVIDE ARCHITECT REPORT ON BULKHEAD

FRAMING BEHIND GREASE HOOD

Corrective Action Required

2 Misc IPC 305.8; IRC P2603 PROTECTION FROM PENETRATION OF PVC /

ABS / PEX / COPPER PLUMBING PIPE LESS THAN 1-1/2" FROM FACE OF FRAMING TO RECEIVE SCREWED OR NAILED COVERING: PROTECT PIPE WITH MINIMUM 1/16" THICK HARDENED STEEL SHIELD PLATES. SHIELD PLATES SHALL COVER THE AREA OF THE MEMBER WHERE THE PIPE PENETRATES. SHIELD PLATES SHALL EXTEND A MINIMUM OF 2" ABOVE BASE PLATES / TRACKS AND BELOW TOP PLATES / TRACKS (USE "BOCA" PLATES WHERE SPACE

ALLOWS). CHECK ALL.

Corrective Action Required

3 Misc IPC 305 PROTECTION OF COPPER PIPING AT POTENTIAL CONTACT

WITH STEEL OR OTHER DISSIMILAR METALS: INSTALL GROMMETS OR OTHER APPROVED PROTECTION FROM SHARP EDGES &

DISSIMILAR METAL.

**Corrective Action Required** 

4 Misc NEC 300-11, 330.30 & 334-10 ENSURE MC ELECTRICAL CABLE: IS

SECURELY FASTENED WITHIN 12" OF ENTRY TO BOXES.

Corrective Action Required

5 Misc NEC 110-12: UNUSED OPENINGS AT ELECTRICAL PANELS /

JUNCTION BOXES NOT PLUGGED. CHECK ALL.

Corrective Action Required

6 Misc PROVIDE JACKSON COUNTY HEALTH DEPARTMENT REPORT ON

BLACKENED AREAS OF DRYWALL FOR POSSIBLE MOLD.

Corrective Action Required

7 Misc NO FURTHER INSPECTIONS WITHOUT CITY-STAMPED PRINTS ON

## JOBSITE -- NOT TO BE USED AS WORKING SET.

**Comments:**