

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT,
MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Wednesday, November 15, 2017
Partial Correction 1 Misc		OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING AND WALLS AT: LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK; CORR 205 WALLS + LID; CORR A-305 LID & WALLS; CORR 405; CORR 219; CORR 207; LOBBY 205; CORR 219; LOBBY 224; LOBBY 309; CORR 305 S; CORR 307; CORR 319; CORR 405; [CORR 419; CORR 407; LOBBY 409; ELEV LOBBY 324 1ST LAYER; UNITS/ROOMS: 201; 203; 204; 206; 209; 210; 212; 217; 218; 221; 222; 225; 226; 227; 228; 229; 231; 232; 233; 234; [213 CHASE 1ST LAYER; UNITS/ROOMS: 301; 303; 304; 306; 308; 310; 312; 313 EXCLUDING CHASE; 321; 322; 325; 326; 328; 332; 333; 334; 314; 315 EXCLUDING CHASE; 316; 317/318; 327; 329; 331; [313 CHASE 1ST LAYER; UNITS/ROOMS: 401; 403; 404; 406; 408; 410; 412; 413 1ST LAYER; 415; 416; 417/418; 421; 422; 425; 426; 427; 428; 431; 432; 433; 434; [429; UNITS/ROOMS: [CHASE AT 513 1ST LAYER; 522 ABOVE CEILING AT S WALL;	
Partial Correction 2 Misc		OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLIES AT STAIRWELLS:	

STAIR 103/202/302/402: FRAMING & ENCLOSED SYSTEMS AT
WELL FACE EXCEPT AT ATTIC ACCESS;

ABOVE CEILING AT BACKSIDE OF STAIRWELL WALL AT: 201; 222;
301; 322; 206; 401; 405/431; 406; 408; 422;

All Rough Inspection - Commercial

John Borns

Partial

Wednesday, November 15,
2017

Partial Correction

1

Misc

OK TO COVER CORRIDOR/LOBBY WALLS AND CEILINGS AT: LINK
CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4; CORR
219; CORR 307/319; LOBBY 409; CORR 507 SHEATHING & RC
CHANNEL; CORR 519 SHEATHING & RC CHANNEL; CORR 419 @
WINDOWS OK TO SHEATH & APPLY RC CHANNEL; CORR
407/409/419; CORR 507/509/519; CORR 419 @ WINDOWS
SHEATHING & RC CHANNEL; LOBBIES 324 & 424 AFTER
FIRE-BLOCKING IS COMPLETE;

Partial Correction

2 Misc

OK TO COVER WHEN READY WALL AND CEILING FRAMING +
SYSTEMS TO BE ENCLOSED AT:

1ST FLOOR SPACES:

[WOOD FRAMING AT 104; 105; 107; 108; 109; TO BE ADDRESSED
BY A/E BEFORE WALLS ARE CLOSED.]

2ND FLOOR UNITS/SPACES: 201; 203; 204; 206; 207; 208; 209;
212; 213; 214; 216; 217; 218; 219; 232; 233; ABOVE CEILING AT
STAIRWELL COMMON WALL AT 201 & 222; 221; 222; 224; 225;
226; 227; 228; 229; 232; 234;

3RD FLOOR UNITS/SPACES: 301; 303, 304, 306; 308; 307; 309;
310; 312; 313 EXCLUDING SHAFT; 314; 315; 316; 318; 321; 322;
325; 326; 327; 328; 329; 331; 332, 333; 334;

4TH FLOOR UNITS/SPACES: 403; 404; 406; 408; 410; 412; 413; 413
AT CHASE; 414; 415; 416; 417/418; 421; 422; 425; 426; 427; 428;
429; 431; 432; 433; 434; 401; TRUSS REPAIR @ 408;

5TH FLOOR UNITS/SPACES: 506; 508; 514; 515; 516(WALL
SHEATHING + RC CHANNEL NOT INCLUDED); 521; 522; 525; 526;
527; 528; **[510; 512; 513; 517/518; 522**

Comments: