

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	John Borns	Failed	Thursday, November 16, 2017

Partial Correction

1	Misc	OK TO COVER CORRIDOR/LOBBY WALLS AND CEILINGS AT: LINK CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4; CORR 219; CORR 307/319; LOBBY 409; CORR 507 SHEATHING & RC CHANNEL; CORR 519 SHEATHING & RC CHANNEL; CORR 419 @ WINDOWS OK TO SHEATH & APPLY RC CHANNEL; CORR 407/409/419; CORR 507/509/519; CORR 419 @ WINDOWS SHEATHING & RC CHANNEL; LOBBIES 324 & 424 AFTER FIRE-BLOCKING IS COMPLETE;
---	------	---

Partial Correction

2	Misc	<p>OK TO COVER WHEN READY WALL AND CEILING FRAMING + SYSTEMS TO BE ENCLOSED AT:</p> <p>1ST FLOOR SPACES: [WOOD FRAMING AT 104; 105; 107; 108; 109; TO BE ADDRESSED BY A/E BEFORE WALLS ARE CLOSED.]</p> <p>2ND FLOOR UNITS/SPACES: 201; 203; 204; 206; 207; 208; 209; 212; 213; 214; 216; 217; 218; 219; 232; 233; ABOVE CEILING AT STAIRWELL COMMON WALL AT 201 & 222; 221; 222; 224; 225; 226; 227; 228; 229; 232; 234;</p> <p>3RD FLOOR UNITS/SPACES: 301; 303, 304, 306; 308; 307; 309; 310; 312; 313 EXCLUDING SHAFT; 314; 315; 316; 318; 321; 322; 325; 326; 327; 328; 329; 331; 332, 333; 334;</p> <p>4TH FLOOR UNITS/SPACES: 403; 404; 406; 408; 410; 412; 413; 413 AT CHASE; 414; 415; 416; 417/418; 421; 422; 425; 426; 427; 428;</p>
---	------	---

429; 431; 432; 433; 434; 401; TRUSS REPAIR @ 408;

5TH FLOOR UNITS/SPACES: 506; 508; 514; 515; 516(WALL SHEATHING + RC CHANNEL NOT INCLUDED); 521; 522; 525; 526; 527; 528; 510; 512; 513; 517/518;

Rated Assembly Inspection

John Borns

Partial

Thursday, November 16, 2017

Partial Correction

1

Misc

OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING AND WALLS AT:

LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK;
CORR 205 WALLS + LID; CORR A-305 LID & WALLS; CORR 405;
CORR 219; CORR 207; LOBBY 205; CORR 219; LOBBY 224; LOBBY 309; CORR 305 S; CORR 307; CORR 319; CORR 405; CORR 419;
CORR 407; LOBBY 409; ELEV LOBBY 324 1ST LAYER; **[LOBBY 424;**

UNITS/ROOMS: 201; 203; 204; 206; 209; 210; 212; 217; 218; 221; 222; 225; 226; 227; 228; 229; 231; 232; 233; 234; [213 CHASE 1ST LAYER;

UNITS/ROOMS: 301; 303; 304; 306; 308; 310; 312; 313
EXCLUDING CHASE; 321; 322; 325; 326; 328; 332; 333; 334; 314;
315 EXCLUDING CHASE; 316; 317/318; 327; 329; 331; [313 CHASE 1ST LAYER;

UNITS/ROOMS: 401; 403; 404; 406; 408; 410; 412; 413 1ST LAYER;
415; 416; 417/418; 421; 422; 425; 426; 427; 428; 431; 432; 433;
434; 429;

UNITS/ROOMS: CHASE AT 513 1ST LAYER; 522 ABOVE CEILING AT S WALL;

Partial Correction

2

Misc

OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLIES AT STAIRWELLS:
STAIR 103/202/302/402: FRAMING & ENCLOSED SYSTEMS AT WELL FACE EXCEPT AT ATTIC ACCESS;

ABOVE CEILING AT BACKSIDE OF STAIRWELL WALL AT: 201; 222; 301; 322; 206; 401; 405/431; 406; 408; 422;

Comments: