Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171839, Building Permit - Residential
Address: 4012 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Gas Service Inspection - Residential	Dale Carter	Passed	Tuesday, November 21, 2017	
All Rough Inspection - Residential	Dale Carter	Failed	Tuesday, November 21, 2017	
Corrective Action Require 1 Misc		 EXT: Siding nails overdriven; ensure WSP spacing where needed. 12. 1st FLR: Firestop at change of ceiling height in living room - foam gaps in blocking. 13. 1st FLR: Firestop vert-to-horiz where fireplace meets arches and where arch meets perimeter wall - foam gaps. 21. 1st FLR: Many corrections needed in roof framing - too numerous to itemize, but include issues such as missing purlins, missing supports, and incorrectly constructed supports. 		
Gas Piping Inspection - Residential	Dale Carter	Passed	Tuesday, November 21, 2017	