

# Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRRES20172142, Building Permit - Residential

Address: 1615 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Dale Carter	Failed	Wednesday, November 22, 2017

### Corrective Action Required

1	Misc	6. BSMT: Slope & support DWV. 11. 1st FLR: More than two consecutive load-bearing studs have been bored along the north wall. 12. 1st FLR: Slope & support DWV in attic. 18. EXT: Siding nails are overdriven; ensure WSP spacing where needed.
---	------	--

<b>Erosion Control</b>	Dale Carter	Partial	Wednesday, November 22, 2017
------------------------	-------------	---------	------------------------------

### Partial Correction

1	Misc	Compliant. Maintain.
---	------	----------------------

### Comments: