

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20172142, Building Permit - Residential

Address: 1615 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Monday, November 27, 2017

Corrective Action Required

1	Misc	11. 1st FLR: More than two consecutive load-bearing studs have been bored along the north wall. *Pipe has been rerouted, but studs have not been repaired/sistered. OK to rock all but this location.
---	------	--

Comments: