

# Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                              | Inspector: | Outcome: | Date:                     |
|--|------------|----------|---------------------------|
| <b>All Rough Inspection - Commercial</b> | John Borns | Partial  | Friday, December 01, 2017 |

### Partial Correction

|   |      |   |
|---|------|---|
| 1 | Misc | OK TO COVER CORRIDOR/LOBBY WALLS AND CEILINGS AT: LINK CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4; CORR 219; CORR 307/319; LOBBY 409; CORR 507 SHEATHING & RC CHANNEL; CORR 519 SHEATHING & RC CHANNEL; CORR 419 @ WINDOWS OK TO SHEATH & APPLY RC CHANNEL; CORR 407/409/419; CORR 507/509/519; CORR 419 @ WINDOWS SHEATHING & RC CHANNEL; LOBBIES 324 & 424 AFTER FIRE-BLOCKING IS COMPLETE; |
|---|------|---|

### Partial Correction

|   |      |  |
|---|------|--|
| 2 | Misc | <p>OK TO COVER WHEN READY WALL AND CEILING FRAMING + SYSTEMS TO BE ENCLOSED AT:</p> <p>1ST FLOOR SPACES:<br/><b>[WOOD FRAMING AT 104, 105, 107, 108, 109 FIRE-PROTECTED &amp; INSPECTED BY 3RD PARTY INSPECTOR</b></p> <p>2ND FLOOR UNITS/SPACES: 201; 203; 204; 206; 207; 208; 209; 212; 213; 214; 216; 217; 218; 219; 232; 233; ABOVE CEILING AT STAIRWELL COMMON WALL AT 201 &amp; 222; 221; 222; 224; 225; 226; 227; 228; 229; 232; 234;</p> <p>3RD FLOOR UNITS/SPACES: 301; 303, 304, 306; 308; 307; 309; 310; 312; 313 EXCLUDING SHAFT; 314; 315; 316; 318; 321; 322; 325; 326; 327; 328; 329; 331; 332, 333; 334;</p> <p>4TH FLOOR UNITS/SPACES: 403; 404; 406; 408; 410; 412; 413; 413 AT CHASE; 414; 415; 416; 417/418; 421; 422; 425; 426; 427; 428;</p> |
|---|------|--|

Partial Correction  
3 Misc

429; 431; 432; 433; 434; 401; TRUSS REPAIR @ 408;

5TH FLOOR UNITS/SPACES: 506; 508; 510; 512; 513; 514; 515;  
516(WALL SHEATHING + RC CHANNEL NOT INCLUDED); 517/518;  
521; 522; 524; 525; 526; 527; 528;

OK TO COVER WHEN READY FRAMING & SYSTEMS TO BE  
CONCEALED AT CEILING AND WALLS AT STAIRWELLS: STAIRWELL  
#2; **[STAIRWELL #3;**

**Rated Assembly  
Inspection**

John Borns

Partial

Friday, December 01, 2017

Partial Correction  
1 Misc

OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING  
AND WALLS AT:

LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK;  
CORR 205 WALLS + LID; CORR A-305 LID & WALLS; CORR 405;  
CORR 219; CORR 207; LOBBY 205; CORR 219; LOBBY 224; LOBBY  
309; CORR 305 S; CORR 307; CORR 319; CORR 405; CORR 419;  
CORR 407; LOBBY 409; ELEV LOBBY 324 1ST LAYER; LOBBY 424  
EXCEPT CHASE; 524 INCL "ATTIC" LEVEL; CORR 507; CORR 519;  
LOBBY 509; 224 SE & SW CORNERS ONE LAYER; 324 CHASES AT SE  
& SW CORNERS 1ST LAYER; 424 CHASES AT SE & SW CORNERS  
1ST LAYER; 424 CHASES AT SE & SW CORNERS 1ST LAYER; 2ND  
LAYER 5/8" TYPE X AT TWO INNER WALLS AT SE & SW CORNER  
CHASES AT 524, 424, 324, 424; **[FRAMING + SHAFT LINER AT  
TWO OUTER WALLS AT SE & SW CORNER CHASES AT 524, 424;  
324, 224;**

UNITS/ROOMS: 201; 203; 204; 206; 209; 210; 212; 213 CHASE 1ST  
LAYER; 213 CHASE 2ND LAYER AT REAR WALL; 217; 218; 221; 222;  
225; 226; 227; 228; 229; 231; 232; 233; 234;

UNITS/ROOMS: 301; 303; 304; 306; 308; 310; 312; 313  
EXCLUDING CHASE; 313 CHASE 1ST LAYER; 313 CHASE 2ND LAYER  
AT REAR WALL; 321; 322; 325; 326; 328; 332; 333; 334; 314; 315  
EXCLUDING CHASE; 316; 317/318; 327; 329; 331;

UNITS/ROOMS: 401; 403; 404; 406; 408; 410; 412; 413 1ST LAYER;  
413 CHASE 2ND LAYER AT REAR WALL; 415; 416; 417/418; 421;  
422; 425; 426; 427; 428; 429; 431; 432; 433; 434;

UNITS/ROOMS: 506; 508 INCL "ATTIC" LEVEL; 510; 512; CHASE AT  
513 1ST LAYER; 513 INCL 2ND LAYER AT CHASE; 513 CHASE 2ND

Partial Correction  
2 Misc

LAYER AT REAR WALL; 514; 515; 516; 517/518; 521; 522 ABOVE  
CEILING AT S WALL; 522; 525 ; 526; 527; 528;

OK TO COVER WHEN READY COMPONENTS OF RATED  
ASSEMBLIES AT STAIRWELLS:  
STAIR 103/202/302/402: FRAMING & ENCLOSED SYSTEMS AT  
WELL FACE EXCEPT AT ATTIC ACCESS;

ABOVE CEILING AT BACKSIDE OF STAIRWELL WALL AT: 201; 222;  
301; 322; 206; 401; 405/431; 406; 408; 422;

ONE LAYER 5/8" TYPE X AT WELL FACE AT STAIRWELLS: **[#1  
COMPLETE; #2 & #3 PARTIAL;**

**Comments:**