

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFC20171319, Public Works Infrastructure Permit - Commercial  
LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection:                                   | Inspector:    | Outcome: | Date:                           |
|---|---------------|----------|---------------------------------|
| DEI-Erosion Sediment Control (ESC) Inspection | Nick Lightner | Failed   | Monday,<br>December<br>04, 2017 |

Corrective Action Required

1 There are problems with the erosion control devices on your site.

\* ESC fence needs to be added to the W side of the property like the engineering plans call out. I will check back in a few days to see if any thing has been added. Nick Lightner  
12/04/2017 1:10 PM

|                |               |         |                                 |
|----------------|---------------|---------|---------------------------------|
| DEI-Site Visit | Nick Lightner | Partial | Monday,<br>December<br>04, 2017 |
|----------------|---------------|---------|---------------------------------|

Informational

1 Stopped by to introduce my self and called Scott so that he would have my number. Crew was setting up to pour the approach.

**Comments:**