

Temporary Certificate of Occupancy

Permit #: PRCOM20172339
Address: 300 SW BLUE PKWY, Unit:D, LEES SUMMIT, MO 64063
Inspected On: Friday, December 29, 2017
Inspected By: John Borns
Expiration Date: 1/11/2018 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Temporary C of O	Friday, December 29, 2017

Corrective Action Required:

1	Misc	ROOFTOP INSPECTION TO BE REQUESTED AND PERFORMED WHEN READY.
---	------	--

Corrective Action Required:

2	Misc	PLANNING INSPECTION TO BE REQUESTED AND PERFORMED AFTER FACADE IS COMPLETED AND RTU SCREENING IS IN PLACE.
---	------	--

Corrective Action Required:

3	Misc	AFFIX PERMANENT ADDRESS LABEL TO ELECTRICAL SERVICE METER/DISCONNECT
---	------	--

Corrective Action Required:

4	Misc	PERMANENT PATCH OPENING IN EXTERIOR REAR WALL WHERE ELECTRICAL FEEDER CONDUITS ENTER BUILDING.
---	------	--

Corrective Action Required:

5	Misc	GLAZING AT SOUTH ENTRY SUBJECT TO APPROVAL WHEN INSTALLED (MUST BE ETCHED "TEMPERED").
---	------	--

Corrective Action Required:

6 Misc AIRLOCK AT SOUTH ENTRANCE SUBJECT TO APPROVAL WHEN
INSTALLED (GLAZING MUST BE ETCHED "TEMPERED").

Corrective Action Required:

7 Misc HANDRAILS AT SOUTH RAMP AND NORTH ENTRANCE SUBJECT TO
APPROVAL WHEN COMPLETED PERMANENT.

Corrective Action Required:

8 Misc NEC 408.4: LABELING OF ELECTRICAL CIRCUIT POSITIONS AT
PANEL(S): EACH BREAKER POSITION MUST BE LABELED. MUST BE
LEGIBLE, SPECIFIC. IF PANEL SCHEDULE IS USED NUMBER
POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR
CONTINUATION SYMBOLS EXCEPT @ MULTIPLE POLE BREAKERS.
LABEL UNUSED BREAKERS "SPARE".