

CODES ADMINISTRATION

Inspection Summary

Permit #: PRRES20171140, Building Permit - Residential Address: 1522 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Electrical Service Inspection - Residential	Mike Copeland	Passed	Friday, December 29, 2017
Gas Service Inspection - Residential	Mike Copeland	Passed	Friday, December 29, 2017
All Rough Inspection - Residential	Mike Copeland	Failed	Friday, December 29, 2017
	·	Failed	Friday, December 29, 2017
Residential	·	Frame garage portal	s per detail
Residential Corrective Action Require	ed 1. 2.	Frame garage portal Fur out around retur	
Residential Corrective Action Require	ed 1. 2. require	Frame garage portal Fur out around retur ed insulation.	s per detail n air in garage to accommodate
Residential Corrective Action Require	ed 1. 2. require 3.	Frame garage portal Fur out around retur ed insulation. Seal around plumbin	s per detail
Residential Corrective Action Require	ed 1. 2. require 3. master	Frame garage portal Fur out around retur ed insulation. Seal around plumbin r closet.	s per detail n air in garage to accommodate g penetration in return air over
Residential Corrective Action Require	ed 1. 2. require 3. master 4.	Frame garage portal Fur out around retur ed insulation. Seal around plumbin r closet. 2 2x12 over living no	s per detail n air in garage to accommodate
Residential Corrective Action Require	ed 1. 2. require 3. master 4. Land o	Frame garage portal Fur out around retur ed insulation. Seal around plumbin r closet. 2 2x12 over living no on bearing wall by stairs.	s per detail n air in garage to accommodate g penetration in return air over ot designed for purlin support.
Residential Corrective Action Require	ed 1. 2. require 3. master 4. Land o 5.	Frame garage portal Fur out around retur ed insulation. Seal around plumbin r closet. 2 2x12 over living no on bearing wall by stairs. Install stud support f	s per detail rn air in garage to accommodate ng penetration in return air over ot designed for purlin support. For hip rafter over master.
Residential Corrective Action Require	ed 1. 2. require 3. master 4. Land o	Frame garage portal Fur out around retur ed insulation. Seal around plumbin r closet. 2 2x12 over living no on bearing wall by stairs. Install stud support f	s per detail n air in garage to accommodate g penetration in return air over ot designed for purlin support.



CODES ADMINISTRATION

Comments:

220 SE Green Street | Lee's Summit, MO 64063 |816.969.1200 | 816.969.1201 Fax | cityofLS.net/Development