Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20172813, Building Permit - Residential Address: 4015 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: Wednesday, January 03, 2018 **Gas Piping Inspection -** Mike Copeland Passed Residential Gas Service Inspection - Mike Copeland Failed Wednesday, January 03, 2018 Residential Corrective Action Required 1 Misc NOT ENOUGH TEST PRESSURE **Electrical Service** Mike Copeland Wednesday, January 03, 2018 Passed **Inspection - Residential All Rough Inspection -** Mike Copeland Failed Wednesday, January 03, 2018 Residential

Corrective Action Required

1 Misc -STRAP GARAGE PORTAL PER PLANS

- -FUR OUT RETURN AIR TO ACCOMOATE REQUIRED INSULATION.
- -BOCA PLATE PLUMBING 2ND FLOOR BATH TOP PLATE -RAFTERS OVER 1ST FLOOR BATH/CLOSET ARE OVERSPAN,

INSTALL PURLIN.

-2-2x12 OVER LIVING CARRYING ROOF LOAD IS OVERSPAN AND NOT ON THE PLAN. HAVE ENGINEER ADDRESS THE BEAM SIZE OR INSTALL ROOF SUPPORT PER PLAN.

-SHORT WALL OVER 3 LVL, HAVE ENGINEER ADDRESS OR SOLID

BLOCK TO PREVENT LATERAL MOMENT

-INSTALL SECURITY BLOCKING FOR WALKOUT DOOR.

-SOLID BLOCK CANTILEVER FLOOR JOISTS FIREPLACE -JOIST HANGER DOUBLE JOIST ABOVE BASEMENT STAIRS

Comments: