

---

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential  
Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
DEI-Sanitary Sewer Construction Inspection	Brice Lawson	Partial	Wednesday, January 03, 2018

Informational

1 Brice Lawson 11/22/2017 6:18 AM

On 11/21/17 Redford replaced a broken 45 degree bend at the connection to the wye fitting on the sewer lateral for lot 65. The broken 45 degree bend was located due to a leak that was noticed during the air pressure test.

Informational

2 Brice Lawson 12/04/2017 9:45 AM

Redford has removed the stub for lot 75. They removed part of the end of the 4" wye. A stongback ferco was installed and connected the 4" wye to a 45 degree bend. They were installing the stub when I left.

Informational

3 Brice Lawson 01/02/2018 3:20 PM

Redford Construction flushed the following sanitary sewer line segments:

MH D-1 to MH D-2

MH D-1 to MH C-3

MH C-3 to MH C-2

MH C-2 to MH C-1

MH C-1 to MH B-3

MH B-3 to MH B-2

Informational

4 Brice Lawson 01/03/2018 3:28 PM

Redford Construction requested a punch list for the sanitary sewer construction for this site. I performed inspections on the sanitary sewers that have been installed and will send Redford a preliminary punch list.

DEI-Sanitary Sewer  
Construction Inspection

Brice Lawson

Partial

Wednesday,  
January 03,  
2018

Informational

- 1 Brice Lawson 11/22/2017 6:18 AM  
On 11/21/17 Redford replaced a broken 45 degree bend at the connection to the wye fitting on the sewer lateral for lot 65. The broken 45 degree bend was located due to a leak that was noticed during the air pressure test.

Informational

- 2 Brice Lawson 12/04/2017 9:45 AM  
Redford has removed the stub for lot 75. They removed part of the end of the 4" wye. A stongback ferco was installed and connected the 4" wye to a 45 degree bend. They were installing the stub when I left.

Informational

- 3 Brice Lawson 01/02/2018 3:20 PM  
Redford Construction flushed the following sanitary sewer line segments:  
MH D-1 to MH D-2  
MH D-1 to MH C-3  
MH C-3 to MH C-2  
MH C-2 to MH C-1  
MH C-1 to MH B-3  
MH B-3 to MH B-2

Informational

- 4 Brice Lawson 01/03/2018 3:28 PM  
Redford Construction requested a punch list for the sanitary sewer construction for this site. I performed inspections on the sanitary sewers that have been installed and will send Redford a preliminary punch list.

Informational

- 5 Brice Lawson 01/03/2018 3:32 PM  
Redford Construction requested a punch list for the sanitary sewer construction for this site. I performed inspections on the sanitary sewers that have been installed and will send Redford a preliminary punch list.

**Comments:**

---