

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161934, Building Permit - Commercial

Address: 783 NW DONOVAN RD, Unit:G2, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	John Borns	Failed	Thursday, January 04, 2018

Corrective Action Required

1 Misc

SILL PLATE ANCHOR BOLTS:

- REQUIRED WITHIN 12" OF END OF EACH PIECE
- ENSURE ALL BOLTS HAVE NUTS AND WASHERS
- CHECK ALL NUTS FOR TIGHTNESS; TIGHTEN AS NEEDED

Corrective Action Required

2 Misc

FIREBLOCK ELECTRICIAN'S TOP PLATE BORES WHERE FALSE WALL WILL BE BUILT TO CREATE INSULATED MECHANICAL CHASE.

Comments: