

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWLD20173826, Public Works Land Disturbance Permit

TAILOR MADE LANDING

Address: 1600 SE HAMBLEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Matt Munger	Partial	Wednesday, January 17, 2018

Corrective Action Required

1 Matt Munger 01/02/2018 10:13 AM

The area along the roadway where the original location construction entrance was going to be put in will need silt fence put in. Rick said in an email on 12/21/17 he was going to order the silt fence.

Corrective Action Required

2 Matt Munger 01/04/2018 9:27 AM

No workers were present. Silt fence from new construction entrance to existing along the roadway has not been installed yet.

Corrective Action Required

3 Matt Munger 01/17/2018 11:25 AM

The silt fence along the street has a large chunk of mud that has rolled over the silt fence pulling it down and will need to be removed and silt fence put back in place. The ESC needs to be checked on a weekly basis to ensure there are not issues with the ESC to prevent silt from leaving the site.

Comments: