

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential  
Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Sanitary Sewer - Invert	Brice Lawson	Partial	Friday, January 19, 2018

Corrective Action Required

1 Brice Lawson 01/19/2018 3:14 PM  
Redford installed the invert in the existing manhole #60-082. The invert was installed to connect the new pipe to the existing invert. It appears that the invert is very flat across the manhole with minimal slope. It appears that water is collecting in the mouth of the new sanitary pipe and possibly holding in the new pipe.

Verify that there is enough slope from the F/L in of the new pipe to the F/L out of the existing pipe.

Comments: