

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20171319, Public Works Infrastructure Permit - Commercial
LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Tuesday, January 23, 2018

Corrective Action Required

- 1 There are problems with the erosion control devices on your site. The contractor still has made no effort to get the erosion control put up, by either the silt fence or mulch. I have spoke with Khanh and he said he will give not more inspections until the erosion control has been installed.Steve Robbins 01/23/2018 11:13 AM

Comments: