

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161769, Building Permit - Commercial

Address: 825 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Friday, February 09, 2018

Partial Correction

1 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT STAIRWELLS:

EAST STAIRWELL:

1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY; 2ND LAYER WALLS ONLY;

2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK;

3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER;

4TH FLOOR: STAIRWELL FACE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER;

STAIR SHAFT WALL GWB AT UNIT FACE AND CORRIDOR FACE:

[1ST LAYER;

TOWER ABOVE 4TH FLOOR: 1ST LAYER AT HIGH CEILING & WALLS; **[3RD LAYER + HAT CHANNEL AT HIGH CEILING & WALLS; 1ST LAYER AT LOW CEILINGS;**

WEST STAIRWELL:

1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY; 2ND LAYER WALLS ONLY;

2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK;

3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER;

4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS
1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS
2ND LAYER;

**STAIR SHAFT WALL GWB AT UNIT FACE AND CORRIDOR FACE:
[1ST LAYER;**

**TOWER ABOVE 4TH FLOOR: 1ST LAYER AT HIGH CEILING &
WALLS; [3RD LAYER + HAT CHANNEL AT HIGH CEILING & WALLS;
1ST LAYER AT LOW CEILINGS;**

Partial Correction

2 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT ELEVATOR
SHAFT:

1ST FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PRE-ROCK

2ND FLOOR: 1ST LAYER PRE-ROCK;

3RD FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PREROCK

ELEVATOR SHAFT WALL GWB AT UNIT FACE AND CORRIDOR
FACE:

4TH FLOOR: [1ST LAYER;

All Rough Inspection - John Borns

Partial

Friday, February 09, 2018

Commercial

Partial Correction

1 Misc

OK TO COVER WHEN READY FRAMING AND ENCLOSED SYSTEMS
AT:

SHOWER WALLS AT FLOORS: #4, 3, 2, 1; BEHIND SHOWERS AT
4TH & 3RD FLOORS; STAIR TOWER CEILING & WALLS ABOVE 4TH
FLOOR;

**ELEVATOR SHAFT INTERIOR FACE OK TO COVER AT:
[4TH FLOOR;**

4TH FLOOR CEILINGS & WALLS OK TO COVER; RC CHANNEL
COMPLETE;

[3RD FLOOR CEILINGS & WALLS OK TO COVER;

1ST FLOOR: WALL CAVITIES AT SHEAR WALLS OK TO COVER;

Comments: