

Certificate of Occupancy

Permit #: PRCOM20161178
Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081
Inspected On: Monday, February 12, 2018
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Monday, February 12, 2018

Comments: REMAINING ISSUES AT ROOFTOP TO BE CORRECTED PRESENTLY...

- 1. PROTECTION OF ROOF MEMBRANE UNDER WOODEN PIPING SUPPORT BLOCKS FOR ROOFTOP EQUIPMENT AND GAS PIPING: ROOF MEMBRANE-COMPATIBLE SLIP SHEETS TO UNDERSIDE OF BLOCKS WITH METAL FASTENERS AT SIDES OF BLOCKS.**
- 2. ELECTRICAL RECEPTACLE AT UNIT DHUM-1 SHOWS OPEN GROUND. REPAIR OR REPLACE.**

THEN OK FOR USE & OCCUPANCY