

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20161876, Public Works Infrastructure Permit - Residential
Napa Valley 3rd Plat Street/Storm/MDP/ESC, sanitary sewer

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Matt Munger	Failed	Tuesday, February 20, 2018

Corrective Action Required

1 Matt Munger 02/08/2018 2:52 PM There are problems with the erosion control devices on your site.

1530 SW Blackstone PL. has silt fence down on the SW Napa Valley Dr. side as well as corrugated pipe laying on top of the silt fence behind that address.

ESC needs to be intact on all lots that have not had vegetation established to ensure silt does not leave the site. ESC devices used in curb inlets need to be maintained periodically to ensure they are working properly.

Corrective Action Required

2 Matt Munger 02/14/2018 10:42 AM
ESC needs to be intact and maintained to be in compliance. There is a home on the corner of SW Blackstone Pl and Napa Valley Dr that the silt fence is down. Behind that home the silt fence has storm pipe laying over the fence. Failure to maintain ESC can result in a Stop Work Order.

Corrective Action Required

3 Matt Munger 02/20/2018 1:38 PM
The swale that runs between the houses off SW Napa Valley Dr. and SW Blackstone Pl is holding water. Run off from the swale is running over into the backyard of 1709 SW Napa Valley Dr. and other backyards off SW Napa Valley Dr that back up to the swale.

The gutter devices off of SW Napa Valley Dr. going into the 3rd Plat is not draining properly. The silt fence has been breached as well up from the curb inlets. ESC needs to be in place

and maintained to be in compliance.

Comments:
