

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #:	PRCOM20172129
Address:	834 SW BLUE PKWY, LEES SUMMIT, MO 64063
Inspected On:	Tuesday, February 27, 2018
Inspected By:	John BornsJohn BornsJohn Borns
Expiration Date:	3/15/2018 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Temporary C of O	Tuesday, February 27, 2018

Corrective Action Required:

1 Misc BACKFLOW PREVENTION DEVICE REQUIRED AT WATER-PIPED DISH WASHER

Corrective Action Required:

2 Misc VACUUM BREAKER REQUIRED AT HOSE BIB AT KITCHEN

Corrective Action Required:

3 Misc NEC 110-22; 384-13; IRC E3606.2 PANEL SCHEDULES / LABELING OF ELECTRICAL CIRCUIT BREAKERS: EACH BREAKER MUST BE LABELED WITH REFERENCE TO SPECIFIC SPACE(S) OR EQUIPMENT SERVED. MUST BE LEGIBLE; SPECIFIC. NO DITTO MARKS OR CONTINUATION SYMBOLS FOR INDIVIDUAL BREAKERS. LABEL UNUSED BREAKERS "SPARE"

Corrective Action Required:

4	Misc	PAINT NEW ROOFTOP GAS PIPING 100%
Correctiv	e Action Require	d:

5 Misc RESOLVE ANY FIRE DEPARTMENT ISSUES