LEE'S SUMMIT M I S S O U R I

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20162552, Public Works Infrastructure Permit - Commercial SUMMIT SQUARE APPARTMENTS Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:					
Inspectio	on:	Inspector:	Outcome:	Date:	
DEI-Erosion Sediment Control (ESC) Inspection		Steve Robbins	Passed	Monday, March 05, 2018	
Informational					
1	1 The erosion control is in good condition and has no problems at this time.				
Informational					
2 The erosion control is in place. There are no issues at this time.					
Informational					
3	The erosion control is in place. Steve Robbins 12/27/2017 1:32 PM				
Informational					
4	The erosion control behind the buildings is in place and seems to be working. Steve Robbins 01/19/2018 2:18 PM				
Informational					
5	The erosion control is in place , they are using mulch berms instead of silt fence. Everything looks good.Steve Robbins 02/01/2018 1:45 PM				
Corrective Action Required					
6	There is some run-off by building 6 , I talked with Jonathon Myers and they will get some silt fence up as soon as the weather lets up in the next day or so.Steve Robbins 02/20/2018 11:04 AM				
Corrective Action Required					
7	There are problems with the erosion control devices on your site. They did not get the silt fence up, I asked the on- site contractor to take care of it and the mud in the parking lot. He said he would today.Steve Robbins 02/27/2018 4:10 PM				
Corrective Action Required					
8	Meyers and he said h	not doing an inspection unti ne would get in up today.Stev	•		
Resolved					

9 The silt fence has been installed in the ares's that were needed. Steve Robbins 03/05/2018 2:37 PM

Comments: