

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20172899, Building Permit - Residential

Address: 4705 NE GATEWAY DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Jeremy Young	Passed	Monday, March 05, 2018

Informational

Jeremy Young 03/05/2018 3:38 PM Inspected the driveway pour for the property. The cross slope between the sidewalk was between .04-1.8% which is within specs for ADA. There is a solid joint between the right of way and the other driveway. The contractor had placed the expansion joint between the curb and driveway.

DEI-Sidewalk Inspection	Jeremy Young	Passed	Monday,
			March 05,
			2018

Informational

Jeremy Young 02/27/2018 8:41 AM Met the contractor on site. The sidewalk has sufficient rock base at least 4" compacted material. I checked the cross slope and there was approx 1.4-1.6% all the way through the sidewalk.

Informational

2 Jeremy Young 03/05/2018 3:43 PM Inspected the sidewalk after the concrete pour. The contractor met the ADA standards. He was between .04-1.8% cross slope. The contractor used the correct concrete.

Occupancy Inspection - Codes Mike Copeland	Not Ready	Monday,
Residential		March 05,
		2018

Corrective Action Required

1	DENIED DUE TO LACK OF EROSION CONTROL.
	DEINIED DOE TO LACK OF ENGLISHINGE

Erosion Control Mike Copeland Failed Monday, March 05, 2018

Corrective Action Required

REQUESTED INSPECTION DENIED.
 NO EROSION CONTROL IN PLACE.

Comments: