

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSITE20180252, Development - Site

TAILOR MADE LANDING

Address: 1600 SE HAMBLEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Storm - Sewer Construction Inspection	John DiMauro	Partial	Wednesday, March 14, 2018

Informational

1 The crew was working on the stom sewer line on Friday 3/9/18

There were issues with the storm line from the detention basin the the existing field inlet not lining up.

DEI-Storm - Sewer	John DiMauro	Partial	Wednesday,
Construction Inspection			March 14,
			2018

Informational

1 The crew was working on the stom sewer line on Friday 3/9/18

There were issues with the storm line from the detention basin th the existing field inlet not lining up.

DEI-Storm - Sewer	John DiMauro	Partial	Wednesday,
Construction Inspection			March 14,
			2018

Informational

1 The crew was working on the stom sewer line on Friday 3/9/18

There were issues with the storm line from the detention basin th the existing field inlet

not lining up.

Informational

2 John DiMauro 03/13/2018

Kent Monter and I met with the contractors on site to discuss the issues with the storm line from the detention basin to the existing field inlet.

The flow lines on the field inlet and basin outlet and not matching the approved plans.

Co	m	m	e	n	ts	•