

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20170715, Building Permit - Residential

Address: 3352 SW JESSIE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Brice Lawson	Passed	Wednesday, March 14, 2018

Informational

1 Brice Lawson 03/14/2018 8:24 AM
The driveway approach has been installed. The cross slope of the sidewalk through the driveway is less than 2.0%. 4K KCMMB concrete mix was used.

Miscellaneous Inspection	Brice Lawson	Partial	Wednesday, March 14, 2018
--------------------------	--------------	---------	---------------------------------

Corrective Action Required

1 Brice Lawson 03/14/2018 8:27 AM
There is a part of the curb that is broken in front of the driveway approach. It appears that the curb has been broken for some time. I asked the contractor to patch this area when the driveway approach was being poured. He said he would take care of it. The sidewalk still needs to be installed, so I will remind him to patch the curb at the sidewalk inspection.

Comments: