Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20173427, Building Permit - Residential Address: 1349 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, March 14, 2018

Residential

Corrective Action Required

**EROSION CONTROL SHALL BE IN COMPLIANCE

FRAMING:

- -Provide plan on site
- -Nail hanger at IvI-IvI connection above basement stair
- -Anchor steel column
- -Fb dead space at front basement bedroom
- -Fb basement wall space from furdown
- -Provide full bearing support for IvI point load in return air space outside master bedroom
- -Land roof support struts to bearing wall: above dryer,

laundry/foyer; smaller master closet

- -Full blocking under lvl point load at stair
- -Brace ends of IvI beam above kitchen from rotation
- -Anchor sill plates within 12" of breaks

MECHANICAL:

-Pan off return air from fireplace space

ELECTRICAL:

- -Wall receptacle spacing not compliant in basement
- -Protect SE cable at basement bed wall top plate
- -Receptacle within 25 ft of ac

PLUMBING:

-Protect refrigerator water line and wiring

**OK TO INSULATE

Electrical Service Khanh Nguyen Failed Wednesday, March 14, 2018 **Inspection - Residential**

Corrective Action Required

1 -Ground service. Make sure connection is accessible

-Close excessive hole at bottom of service disconnect

Gas Service Inspection - Khanh Nguyen Passed Wednesday, March 14, 2018

Residential

Erosion Control Khanh Nguyen Failed Wednesday, March 14, 2018

Corrective Action Required

1 DCM1 Erosion Control EROSION CONTROL REQUIRED ALONG THE STREET AND GRAVEL

AT DRIVEWAY. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

**YOU ARE REQUIRED TO MAINTAIN EROSION CONTROL

AROUND YOUR PLOT THROUGHOUT THE CONSTRUCTION PHASE.

I CANNOT ALLOW FURTHER INSPECTION UNTIL EROSION

CONTROL IS IN COMPLIANCE

Comments: