

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRRES20171187,

Address: 3400 SW LOIS LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection:             | Inspector:    | Outcome: | Date:                           |
|-------------------------|---------------|----------|---------------------------------|
| DEI-Sidewalk Inspection | Troy Thompson | Failed   | Wednesday,<br>March 21,<br>2018 |

Corrective Action Required

- 1 TTHOMPSON 03/21/2018 10:21 AM  
Matt M. and I checked the forms for the sidewalk and the ADA forms for the turning space area did not meet specifications. The sidewalk forms were not set to 4' to match the existing sidewalk. We gave the contractor the LS detail sheet with all the ADA requirements. We also noticed there was not enough gravel in the driveway approach, we asked the contractor to bring in more gravel and ensure they can get 6" of concrete on top of the compacted gravel.

Comments: