
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSITE20180252, Development - Site

TAILOR MADE LANDING

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Driveway Inspection	John DiMauro	Partial	Wednesday, March 21, 2018

Informational

1 John DiMauro 03/21/2018 3:00 PM

Jeremy Young and I met on site with Rick from Tailor Made to go over the commercial driveway approach plans. There is concern with the curb for the approach being close to Hamblen road which does not have a shoulder.

I will discuss this with the engineering department to come up with a solution.

DEI-Miscellaneous PWORKS Inspection	John DiMauro	Partial	Wednesday, March 21, 2018
-------------------------------------	--------------	---------	---------------------------------

Informational

1 Matt Munger 03/20/2018 2:33 PM

No activity on site. The contractor had set the vault for the Backflow Preventer. The pit on either side of the road was full of water.

DEI-Miscellaneous PWORKS Inspection	Jeremy Young	Partial	Wednesday, March 21, 2018
-------------------------------------	--------------	---------	---------------------------------

DEI-Driveway Inspection	Jeremy Young	Partial	Wednesday,
-------------------------	--------------	---------	------------

March 21,
2018

Informational

1 John DiMauro 03/21/2018 3:00 PM

Jeremy Young and I met on site with Rick from Tailor Made to go over the commercial driveway approach plans. There is concern with the curb for the approach being close to Hamblen road which does not have a shoulder.

I will discuss this with the engineering department to come up with a solution.

Comments:
