

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20170794, Public Works Infrastructure Permit - Residential  
Eagle Creek 15th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Tom Chandler	Failed	Tuesday, March 27, 2018

Corrective Action Required

1 There are problems with the erosion control devices on your site. Tom Chandler  
03/05/2018 8:19 AM Additional devices needed to site until stabization has been  
completed.

Corrective Action Required

2 There are problems with the erosion control devices on your site.Tom Chandler  
03/19/2018 3:47 PM Repairs needed to existing devices.

Corrective Action Required

3 There are problems with the erosion control devices on your site.Tom Chandler  
03/27/2018 10:48 AM The swales are not installed according to plan and no stablization in  
the swales as well. Entire site has no stabilization.

Comments: