

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Wednesday, March 28, 2018

Corrective Action Required

Your project is in violation of the Erosion and Sediment control policy. The silt fence needs to be put back up. Steve Robbins 03/22/2018 1:37 PM

Corrective Action Required

- The have not put up the silt fence yet. Steve Robbins 03/26/2018 2:40 PM Corrective Action Required
- Your project is in violation of the Erosion and Sediment control policy. I sent Doug and e-mail for the second time letting him know of this problem, he has not responded. I will no longer do any inspections after friday and will notify the building inspector. Steve Robbins 03/28/2018 9:34 AM

Comments: