
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20170812, Building Permit - Residential

Address: 1622 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Matt Munger	Failed	Tuesday, April 03, 2018

Corrective Action Required

1 Matt Munger 04/03/2018 10:18 AM

No corrections have been made to fix the ESC issues. The contractor has not responded to emails about the corrections that need to be made.

Comments:
