

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20172813, Building Permit - Residential

Address: 4015 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Matt Munger	Failed	Tuesday, April 03, 2018

Corrective Action Required

1 Matt Munger 04/03/2018 10:23 AM
No corrections to fix the ESC issues have been done. The contractor has not responded to emails about the issues either.

Erosion Control	Matt Munger	Failed	Tuesday, April 03, 2018
-----------------	-------------	--------	----------------------------

Corrective Action Required

1 Matt Munger 04/03/2018 1:45 PM
No corrections have been made to fix the Erosion Control issues as well as any cleanup/repairs to the neighboring yards that were affected by the failed Erosion Control.

Comments: