
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20171839, Building Permit - Residential

Address: 4012 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Matt Munger	Failed	Tuesday, April 03, 2018

Corrective Action Required

1 Matt Munger 04/03/2018 1:56 PM

The site does not have Erosion Control Devices in place to prevent soil from leaving the site. There are signs of silt in the curb gutter due to the lack of ESC devices. Erosion Control needs to be put in place within 48 hours. A Stop Work Order may be issued if ESC devices are not installed.

Comments:
